

# DIN EN ISO 19085-15:2022-05 (E)

## Woodworking machines - Safety - Part 15: Presses (ISO 19085-15:2021)

---

### Contents

	Page
<b>European foreword</b>	<b>4</b>
<b>Annex ZA (informative) Relationship between this European Standard and the essential requirements of EU Directive 2006/42/EC aimed to be covered</b>	<b>5</b>
<b>Foreword</b>	<b>7</b>
<b>Introduction</b>	<b>8</b>
<b>1 Scope</b>	<b>10</b>
<b>2 Normative references</b>	<b>11</b>
<b>3 Terms and definitions</b>	<b>12</b>
<b>4 List of significant hazards</b>	<b>21</b>
<b>5 Safety requirements and measures for controls</b>	<b>23</b>
5.1 Safety and reliability of control systems	23
5.2 Control devices	23
5.3 Start	24
5.4 Safe stops	24
5.4.1 General	24
5.4.2 Normal stop	24
5.4.3 Operational stop	25
5.4.4 Emergency stop	25
5.5 Braking function of tool spindles	25
5.6 Mode selection	25
5.7 Spindle speed changing	25
5.7.1 Spindle speed changing by changing belts on the pulleys	25
5.7.2 Spindle speed changing by incremental speed change motor	25
5.7.3 Infinitely variable speed by frequency inverter	25
5.8 Failure of any power supply	25
5.9 Manual reset control	26
5.10 Enabling control	26
5.11 Machine moving parts speed monitoring	26
5.12 Time delay	26
<b>6 Safety requirements and measures for protection against mechanical hazards</b>	<b>26</b>
6.1 Stability	26
6.1.1 General	26
6.1.2 Displaceable machines	27
6.2 Risk of break-up during operation	27
6.3 Tool holder and tool design	27
6.3.1 General	27
6.3.2 Spindle locking	27
6.3.3 Circular saw blade fixing devices	27
6.3.4 Flange dimensions for circular saw blades	28
6.4 Braking	28
6.4.1 Braking of tool spindles	28
6.4.2 Maximum run-down time	28
6.4.3 Brake release	28

6.5	Safeguards.....	28
6.5.1	Fixed guards.....	28
6.5.2	Interlocking moveable guards.....	28
6.5.3	Hold-to-run control.....	28
6.5.4	Two hand control.....	28
6.5.5	Electro-sensitive protective equipment (ESPE) .....	28
6.5.6	Pressure sensitive protective equipment (PSPE) .....	28
6.6	Prevention of access to moving parts.....	29
6.6.1	General .....	29
6.6.2	Guarding of tools .....	29
6.6.3	Guarding of drives .....	29
6.6.4	Guarding of shearing and/or crushing zones .....	29
6.7	Impact hazard .....	33
6.8	Clamping devices .....	33
6.9	Measures against ejection .....	34
6.9.1	General .....	34
6.9.2	Guards materials and characteristics .....	34
6.10	Work-piece support and guides .....	34
<b>7</b>	<b>Safety requirements and measures for protection against other hazards .....</b>	<b>35</b>
7.1	Fire .....	35
7.2	Noise .....	35
7.2.1	Noise reduction at the design stage .....	35
7.2.2	Noise emission measurement and declaration .....	36
7.3	Emission of chips and dust .....	36
7.4	Electricity .....	37
7.4.1	General .....	37
7.4.2	Displaceable machines .....	38
7.5	Ergonomics and handling .....	38
7.6	Lighting .....	38
7.7	Pneumatics .....	38
7.8	Hydraulics .....	38
7.9	Electromagnetic compatibility .....	38
7.10	Laser .....	38
7.11	Static electricity .....	38
7.12	Errors of fitting .....	38
7.13	Isolation .....	38
7.14	Maintenance .....	39
7.15	Extreme temperatures .....	39
<b>8</b>	<b>Information for use .....</b>	<b>39</b>
8.1	Warning devices .....	39
8.2	Marking .....	39
8.2.1	General .....	39
8.2.2	Additional markings .....	39
8.3	Instruction handbook .....	39
8.3.1	General .....	39
8.3.2	Additional information .....	40
<b>Annex A</b> (informative) <b>Performance level required .....</b>	<b>41</b>	
<b>Annex B</b> (normative) <b>Tests for braking function .....</b>	<b>42</b>	
<b>Annex C</b> (normative) <b>Stability test for displaceable machines .....</b>	<b>43</b>	
<b>Annex D</b> (normative) <b>Impact test for guards .....</b>	<b>44</b>	
<b>Annex E</b> (normative) <b>Noise test code .....</b>	<b>45</b>	
<b>Bibliography .....</b>	<b>51</b>	