

DIN EN ISO 22476-1:2023-04 (E)

Geotechnical investigation and testing - Field testing - Part 1: Electrical cone and piezocone penetration test (ISO 22476-1:2022)

Contents	Page
European foreword	4
Foreword	5
Introduction	6
1 Scope	7
2 Normative references	7
3 Terms, definitions and symbols	7
3.1 Terms and definitions	8
3.2 Symbols	14
4 Equipment	17
4.1 General	17
4.1.1 Tolerances	17
4.1.2 Gaps and soil seals	17
4.2 Cone penetrometer	17
4.3 Surface roughness and hardness	17
4.4 Cone	18
4.5 Friction sleeve	19
4.6 Filter element	20
4.6.1 General filter location	20
4.6.2 Pore pressure u_1	20
4.6.3 Pore pressure u_2	21
4.6.4 Pore pressure u_3	21
4.7 Pushrods	21
4.8 Measuring system	21
4.8.1 Accuracy	21
4.8.2 Sensors for cone resistance and sleeve friction	22
4.8.3 Sensor for pore pressure	22
4.8.4 Sensor for inclination	22
4.8.5 Sensor for temperature	22
4.8.6 Measuring of penetration length	22
4.8.7 Raw data	22
4.9 Thrust machine	23
5 Test procedures	23
5.1 Selection of equipment, procedures and evaluation of results	23
5.1.1 General	23
5.1.2 Calibration and verification requirements	23
5.1.3 Cone penetrometer class conformity assessment	24
5.2 Position and verticality of thrust machine	26
5.3 Preparation of the test	26
5.4 Pushing of the cone penetrometer	27
5.5 Use of friction-reducing techniques	27
5.6 Frequency of test data recording	27
5.7 Registration of penetration length	27
5.8 Pore pressure dissipation test (PPDT)	28
5.9 Test completion	28
5.10 Evaluation of CPT/CPTU in relation to test category	29
5.11 Equipment checks and calibrations	30
5.12 Safety requirements	30

6	Test results.....	30
6.1	Measured parameters.....	30
6.2	Correction of parameters.....	31
6.3	Calculated parameters	33
7	Reporting.....	33
7.1	General.....	33
7.2	Reporting of test results	33
7.2.1	General information.....	33
7.2.2	Location of the test.....	34
7.2.3	Test equipment.....	34
7.2.4	Test results	35
7.3	Presentation of test results.....	36
Annex A (informative) Suitability of test methods.....		37
Annex B (normative) Maintenance, checks and calibration.....		40
Annex C (informative) Calibration report example.....		58
Annex D (normative) Calculation of penetration depth.....		68
Annex E (informative) Correction of sleeve friction for water pressure.....		69
Annex F (informative) Preparation of the piezocone		70
Annex G (informative) Friction reduction techniques		71
Bibliography.....		72