

# DIN ISO 8690:2022-10 (E)

## Measurement of radioactivity - Gamma ray and beta emitting radionuclides - Test method to assess the ease of decontamination of surface materials (ISO 8690:2020)

---

Contents	Page
National foreword .....	3
National Annex NA (informative) Bibliography .....	4
Foreword .....	5
Introduction .....	6
1 Scope .....	7
2 Normatives references .....	7
3 Terms, definitions and symbols .....	8
3.1 Terms and definitions .....	8
3.2 Symbols .....	9
4 Principle .....	10
5 Apparatus .....	10
6 Contamination and decontamination agents .....	12
6.1 Contaminant solutions .....	12
6.1.1 Composition of contaminant solutions .....	12
6.1.2 Preparation of the contaminant solutions .....	12
6.1.3 Preparation of contaminant solution using neutron activation .....	13
6.1.4 Storage of the contaminant solution .....	14
6.2 Decontaminant solution .....	14
7 Test specimens .....	14
7.1 Preparation and preliminary testing .....	14
7.1.1 Resistance to cleaning solution .....	14
7.1.2 Test specimens of non-metallic materials .....	14
7.1.3 Test specimens of metallic materials .....	15
7.2 Number and dimensions .....	15
7.3 Conditioning and cleaning .....	15
8 Procedure .....	16
8.1 Determining the specific pulse rate of each contaminant solution .....	16
8.2 Contamination .....	16
8.3 Decontamination .....	18
8.4 Determining the residual pulse rate .....	19
9 Calculation of results and assessment of ease of decontamination .....	20
10 Test report .....	21
Annex A (informative) Holder for contamination of test specimen .....	22
Annex B (normative) Cage-stirrer apparatus for decontamination .....	24
Annex C (informative) Formulae for preparation of the $^{137}\text{Cs}$ and $^{60}\text{Co}$ contaminant solutions .....	33
Annex D (informative) Calculations for the production of the contaminant solution using neutron activation .....	36
Annex E (informative) Example of a test report .....	38
Bibliography .....	40